

ZAP™ Pads in Action

- In January 2007 a soldier from the US Army's 10th Mountain Division was on patrol in Iraq when he was shot by a sniper.
- The bullet passed through the soldier's Advanced Combat Helmet and lodged in the Zorbium Action Pad™.
- Except for some minor abrasions, the soldier was not injured.
- Slide 2 shows the outside rear of the helmet at point of impact
- Slide 3 shows the hole on the inside of helmet through which the bullet fragments passed
- Slide 4 shows the bullet fragments pulled from the soldier's helmet pad.
- What's inside your helmet?





Round fragments



Damaged pad

